

Carleton Condominium Corporation No. 542
Sandcliffe, Winterburn and Grandcourt

TO: All Owners

FROM: Condominium Management Group
CCC542 Board of Directors

DATE: May 11, 2026

RE: REMINDERS - Bell Fibe

This reminder is for owners and residents who have installed Bell Fibe or who are considering installation in their unit.

While a notice is posted in the utility sheds for Bell technicians, owners are responsible for ensuring that no common elements are damaged during the installation process.

Please note the following requirements:

- No cabling may be run on the exterior of the unit, including siding or brick, at any level.
- No holes may be drilled through siding or brick under any circumstances.
- Installers should use an existing conduit into the unit whenever possible, such as an air-conditioning or HVAC conduit.
- A small hole may be drilled into the basement cement foundation, provided it can be done without causing damage.

Any damage to the common elements resulting from a Bell Fibe installation is the responsibility of the unit owner, who will be required to restore the affected areas to their original condition at their own cost.

In previous years, there have been issues with cables resurfacing as winter snow and frost receded. If an owner or resident experiences issues with their Bell Fibe service, they must contact Bell directly, as the Corporation cannot assist with service or technical matters.

Thank you for your cooperation and understanding.

Should you have any concerns, please contact Christine Rausch, Property Manager (phone 613-237-9519 ext. 109).